

GENWAL COAL COMPANY

P.O. Box 1201 • Huntington, Utah 84528
Telephone (801) 687-9813

RECEIVED
SEP 19 1986

September 12, 1986

**DIVISION OF
OIL, GAS & MINING**

ACT/615/032

Mr. Lowell Braxton
Department of Natural Resources
Division of Oil, Gas and Mining
355 W. North Temple
3 Triad Center
Suite 350
Salt Lake City, Utah 84180-1203

Re: Surface design field change


Dear Lowell,

After discussions in the field on Wednesday, Sept. 10, 1986 with Mr. Randy Harden, Genwal Coal Company would like to change the configuration of the surface facilities. These surface changes would include; 1) changing the slope of the cut bank north of the main pad area from 1.5:1 to .25-.5:1 and 2) increasing the undisturbed area in the northwest corner of the surface facilities. Mr. Harden and myself sketched out a map during the meeting on Wednesday delineating these areas and I believe he has submitted this map to you. We will submit a map depicting the changes on the as built drawings when the site construction has been completed.

I would also like to request a field change for the length of the #3 topsoil stockpile area as depicted on Plate 3-8. Due to the excessive amounts of topsoil encountered in the development of the main pad area additional room will be required to stored all this material. Mr. Leatherwood and myself have discussed the possibility of having to extend this topsoil stockpile during a previous field trip. I have discussed this configuration with the Forest Service representative, Jo Ellis, and she sees no problems with this additional configuration. The pile in question will require an extension of approximately 200' to the east. I will submit a map of the area as soon as our surveyor recovers from a recent illness (Hopefully next week).

If you have any further questions or comments please feel free to contact me at 637-7383. Thank you for your time and consideration.

Sincerely yours,


Andrew C. King

GENERAL - PROPOSED FIELD MODIFICATIONS
JRH - 9/11/86

